



## HR & PACOR New Process (Important)

### Process – I



Send your project to Oxygen Client for finding Impurities

### Process – II



Open HR, and click on Start Menu → **Import Oxygen File (\*.oxg)**  
Also you can change clarity of inclusion in HR by right click to properties

Use "IMPORT" in scan laser mapping panel and has to confirm that  
**Model1=simple\_LM,**  
**Model2=Middle\_LM** and  
**Model3=Complex\_LM**

## Process – III

User can create his own Cutting List for Planning Process. (Only work with 06-Single and 06-Complex methods)

ROUGH  
CLASSIFICATION

Method Selections and  
Optimization

USE Tool option for  
manual selection or  
change in planning

Now Open MARKING  
OUT PANEL

Choose Marking AREA

Save Project and Send  
to PACOR or HR for  
MARKING

Now further process  
done on HR / PACOR

